

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401535149

Receive Date:

02/05/2018

Report taken by:

PETER GINTAUTAS

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

### OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		Phone: <u>(720) 929-4306</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80217-3779</u>
Contact Person: <u>Erik Mickelson</u>	Email: <u>Erik.Mickelson@anadarko.com</u>	Mobile: <u>( )</u>

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 10926 Initial Form 27 Document #: 401439047

#### PURPOSE INFORMATION

- |  |  |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination                                       | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water                   |
| <input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure                  | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation                            | <input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project                       |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste                      | <input type="checkbox"/> Rule 906.c.: Director request   |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____   |

#### SITE INFORMATION

Y Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: <u>LOCATION</u>	Facility ID: <u>302689</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>PALMER X-62N65W 20SENW</u>		Latitude: <u>40.125866</u>	Longitude: <u>-104.689992</u>
		** correct Lat/Long if needed: Latitude: <u>40.120547</u>	Longitude: <u>-104.692084</u>
QtrQtr: <u>SENW</u>	Sec: <u>20</u>	Twp: <u>2N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>
Facility Type: <u>LOCATION</u>	Facility ID: <u>306022</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>FT LUPTON HIGHLANDS-61N66W 9SENE</u>		Latitude: <u>40.068110</u>	Longitude: <u>-104.775780</u>
		** correct Lat/Long if needed: Latitude: <u>40.069233</u>	Longitude: <u>-104.773118</u>
QtrQtr: <u>SENE</u>	Sec: <u>9</u>	Twp: <u>1N</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>
Facility Type: <u>LOCATION</u>	Facility ID: <u>328045</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>HOLTON UNIT B-61N66W 7SWNW</u>		Latitude: <u>40.068280</u>	Longitude: <u>-104.826350</u>
		** correct Lat/Long if needed: Latitude: <u>40.065768</u>	Longitude: <u>-104.825467</u>
QtrQtr: <u>SWNW</u>	Sec: <u>7</u>	Twp: <u>1N</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

Facility Type: LOCATION		Facility ID: 328564		API #:		County Name: WELD	
Facility Name: UPRC-61N68W 25NWSW				Latitude: 40.019389		Longitude: -104.957882	
** correct Lat/Long if needed: Latitude: 40.016881				Longitude: -104.955945			
QtrQtr: NWSW	Sec: 25	Twp: 1N	Range: 68W	Meridian: 6	Sensitive Area? Yes		

Facility Type: LOCATION		Facility ID: 331071		API #:		County Name: WELD	
Facility Name: MORRISON-61N67W 17SENE				Latitude: 40.053267		Longitude: -104.906767	
** correct Lat/Long if needed: Latitude: 40.053358				Longitude: -104.906773			
QtrQtr: SENE	Sec: 17	Twp: 1N	Range: 67W	Meridian: 6	Sensitive Area? Yes		

Facility Type: LOCATION		Facility ID: 331681		API #:		County Name: WELD	
Facility Name: SCHMIDT FEDERAL-61N66W 8SWSW				Latitude: 40.061680		Longitude: -104.806370	
** correct Lat/Long if needed: Latitude: 40.061912				Longitude: -104.805968			
QtrQtr: SWSW	Sec: 8	Twp: 1N	Range: 66W	Meridian: 6	Sensitive Area? Yes		

Facility Type: LOCATION		Facility ID: 336154		API #:		County Name: WELD	
Facility Name: HERMAN WAGNER GAS UNIT-63N68W 25NWNW				Latitude: 40.201694		Longitude: -104.956928	
** correct Lat/Long if needed: Latitude: 40.202602				Longitude: -104.955876			
QtrQtr: NWNW	Sec: 25	Twp: 3N	Range: 68W	Meridian: 6	Sensitive Area? Yes		

Facility Type: TANK BATTERY		Facility ID: 445468		API #:		County Name: WELD	
Facility Name: WILLIAM E. GEE GAS UNIT-62N67W 24SWSE				Latitude: 40.118801		Longitude: -104.835353	
** correct Lat/Long if needed: Latitude:				Longitude:			
QtrQtr: SWSE	Sec: 24	Twp: 2N	Range: 67W	Meridian: 6	Sensitive Area? Yes		

Facility Type: TANK BATTERY		Facility ID: 445931		API #:		County Name: WELD	
Facility Name: T. P. HOLTON GAS UNIT-61N66W 6NWSW				Latitude: 40.076295		Longitude: -104.826094	
** correct Lat/Long if needed: Latitude:				Longitude:			
QtrQtr: NWSW	Sec: 6	Twp: 1N	Range: 66W	Meridian: 6	Sensitive Area? Yes		

## SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Various

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

### Other Potential Receptors within 1/4 mile

Various

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	SOILS	No impacts encountered	Soil sampling and laboratory analysis

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

As required by COGCC rule 905.b, soil and groundwater (if present) samples will be collected when buried or partially buried produced water vessels are removed from service. One soil sample will be collected for laboratory analysis from the area most likely to be impacted directly beneath the water vessel upon removal. If groundwater is encountered below the water vessel, a groundwater sample will be collected for laboratory analysis. Additionally, if groundwater is encountered, four sidewall samples will be collected for field screening. The sidewall sample exhibiting the highest apparent impacts will be submitted for laboratory analysis. The soil samples will be analyzed for total petroleum hydrocarbons (TPH-C6-C36); benzene, toluene, ethylbenzene, total xylenes (BTEX); electrical conductivity (EC); and pH. Analysis for sodium adsorption ratio (SAR) will be conducted should the initial EC concentration exceed the Table 910-1 standards. Groundwater samples will be analyzed for BTEX.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Soil samples were collected from each Site and submitted for laboratory analysis. The soil samples were analyzed for total petroleum hydrocarbons (TPHC6C36); benzene, toluene, ethylbenzene, total xylenes (BTEX); electrical conductivity (EC); and pH.

#### Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

#### Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

#### Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 9

Number of soil samples exceeding 910-1 0

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 0

### NA / ND

-- Highest concentration of TPH (mg/kg) 57

NA Highest concentration of SAR

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 0

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) \

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 910-1

NA Highest concentration of Benzene (µg/l)

NA Highest concentration of Toluene (µg/l)

NA Highest concentration of Ethylbenzene (µg/l)

NA Highest concentration of Xylene (µg/l)

NA Highest concentration of Methane (mg/l)

### Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## **SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Any impacted soils above the concentration levels listed in Table 910-1 will be removed from the excavation. Impacted soils exceeding Table 910-1 standards for only EC, pH, and SAR will not be removed below the root zone, established as 3 feet below ground surface (per COGCC guidance).

## **REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Impacted soils (if present) will be taken to either a licensed disposal facility or to Kerr-McGee's land treatment facility. A site-specific groundwater monitoring plan will be developed for COGCC approval (as appropriate) in the event that groundwater impacts exceeding the Table 910-1 Concentrations Levels are detected.

## **Soil Remediation Summary**

### ☐ In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

### ☐ Ex Situ

\_\_\_\_\_ Excavate and offsite disposal  
\_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_  
\_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

## **Groundwater Remediation Summary**

☐ \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
☐ \_\_\_\_\_ Chemical oxidation  
☐ \_\_\_\_\_ Air sparge / Soil vapor extraction  
☐ \_\_\_\_\_ Natural Attenuation  
☐ \_\_\_\_\_ Other \_\_\_\_\_

## **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

## REMEDATION PROGRESS UPDATE

### PERIODIC REPORTING

**Frequency:** ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other Produced Water Vessel Closure

**Report Type:** ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☒ Other Produced Water Vessel Closure Report

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDATION COMPLETION REPORT

### REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? No

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? No

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

If the facility remains in place, reclamation will not be necessary. If a facility is removed, the site will be restored as closely as possible to its pre-existing grade and reclaimed in accordance with COGCC 1004 series rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### **PRIOR DATES**

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. \_\_\_\_\_

### **SITE INVESTIGATION DATES**

Date of Initial Actions described in Site Investigation Plan (start date). \_\_\_\_\_ 07/08/2014

Date of commencement of Site Investigation. \_\_\_\_\_ 07/08/2014

Date of completion of Site Investigation. \_\_\_\_\_ 03/23/2017

### **REMEDIAL ACTION DATES**

Date of commencement of Remediation. \_\_\_\_\_

Date of completion of Remediation. \_\_\_\_\_

### **SITE RECLAMATION DATES**

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

**OPERATOR COMMENT**

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Erik Mickelson

Title: Senior HSE Representative

Submit Date: 02/05/2018

Email: Erik.Mickelson@anadarko.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: PETER GINTAUTAS

Date: 02/08/2018

Remediation Project Number: 10926

**COA Type****Description**

	Submit reports of site investigation and progress of remediation including results of sampling and analysis on an annual basis or more often until remediation is closed.
--	---

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

401535149	FORM 27-SUPPLEMENTAL-SUBMITTED
401535543	OTHER
401535546	OTHER
401535548	OTHER
401535551	OTHER
401535554	OTHER
401535555	OTHER
401535557	OTHER
401535558	OTHER
401535561	OTHER

Total Attach: 10 Files

**General Comments****User Group****Comment****Comment Date**

Environmental	data submitted for facilities 445931 and 302689 indicate closure request is appropriate for those 2 vault removals	02/05/2018
---------------	--	------------

Total: 1 comment(s)