

Inspection Photos
Location Name: North Washington 8-23
API: 05-001-09666



Wellhead



Battery, 1,8/23 crude storage are the two right tanks.

Inspection Photos
Location Name: North Washington 8-23
API: 05-001-09666



Separator, 1,8/23 is on the left.



Water Tank