

Inspection Photos

API: 05-067-08807

Operator: BP America Production

Inspection Number: 680602472

Inspection Date: 1/17/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), rabbitbrush (*Chrysothamnus nauseosus*), and smooth brome (*Bromus inermis*).



Photo 3. View of the southern portion of the project area from southeastern corner facing westward.