

Inspection Photos

API: 05-067-08206

Operator: Catamount Energy Partners

Inspection Number: 680602474

Inspection Date: 1/17/2018



Photo 1. View from the northwestern edge from the project area facing center.



Photo 2. View of the northwestern portion of the project area from the northwestern edge facing eastward.



Photo 3. View of the western portion of the project area from northwestern edge facing southward.



Photo 4. View of erosional channel approximately 2 feet wide and 18 inches deep in the northwestern portion of the project area.