

Inspection Photos
Location Name: Sack Gas Unit 2-x
API: 05-001-09068



Wellhead



Battery

Inspection Photos
Location Name: Sack Gas Unit 2-x
API: 05-001-09068



Separator



Appears to be unused chemical tank. **Corrective Action:**
Unused equipment, address per rule 603.f