

Inspection: Feb 09, 2018
Ramos 1-23 Pad
Caerus Location ID #334104



Produced and condensate 300 bbl tanks. Lined, bermed and fenced. Signs with emergency and wells information. A sign warning of potential H₂S is posted on the tanks.



Wellheads fenced and labeled. No staining or fluids observed around the wellheads.

Inspection: Feb 09, 2018
Ramos 1-23 Pad
Caerus Location ID #334104



Looking south. Location of the former pit (Closed). Cut slope was re-countered by Noble, who managed this location prior to Caerus. Some vegetation growth on this part of the pad.



Looking north. Fenced wellheads. Horizontal tank is labeled and has secondary containment. No stains, no junk. No vegetation observed in this area.

