

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2018

Submitted Date:

02/12/2018

Document Number:

677400526

**FIELD INSPECTION FORM**

Loc ID 428353 Inspector Name: MONTOYA, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 26580  
Name of Operator: BURLINGTON RESOURCES OIL & GAS LP  
Address: 600 N DAIRY ASHFORD RD  
City: HOUSTON State: TX Zip: 77079

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Carlile, Justin		NiobraraInspections@cop.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428355	WELL	DG	02/07/2018	LO	001-09742	Venturers 41-4H	DG

**General Comment:**

**Location**

**Lease Road:**

Type Main

comment:

Corrective ActionL

Date:

Overall Good:

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type Field Flare

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 428355 Type: WELL API Number: 001-09742 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Neibors B-16 Pusher/Rig Manager: Richard Perez  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 50002 Safety Plan: YES

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: YES  
 Multi-Well: \_\_\_\_\_ Disposal Location: waste management

**Comment:** BMP's around location ok, waste oil and good oil on containments. No trash around location, all pipe on racks, location looks good

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">Rig Inspection</a>	montoyaj	02/12/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677400527	rig [icture and BMP's	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377246">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377246</a>