

Inspection Photos

02/09/2018

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 453932

Inspection Doc. Number: 682503150

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 453932



Photo 1: Photos 1-10 show surface roughening stormwater BMP implemented along the perimeter of the location prior to construction activities.



Photo 2: Ph

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 453932



Photo 3: Photo shows operator expanded surface roughening BMPs as needed to better suit the size of the location during construction activities.



Photo 4:

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 453932



Photo 5: Operator was in the process of salvaging topsoil at time of inspection.



Photo 6:

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 453932



Photo 7:



Photo 8:

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 453932



Photo 9:



Photo 10:



Photo 11: Photo of vegetation on the adjacent reference area. Vegetation observed predominantly Western Wheatgrass, sideoats/blue grama, smooth brome, sand dropsed, threeawn, etc...