

Inspection Photos

02/12/2018

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 450635

Inspection Doc. Number: 682503152

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 450635



Photo 1: Photo of sign at well.



Photo 2: Photo taken from the east end of the location, facing north. Photo of interim reclamation in process.

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 450635



Photo 3: Photo taken from the east end of the location, facing northwest. Photo of interim reclamation in process.



Photo 4: Photo taken from the east end of the location, facing southwest. Photo of interim reclamation in process. Photo also shows areas not reasonable needed for production have been reduced and ripped for compaction alleviation. However, 1003.c requires operator to cross-rip; location appears to have only been ripped once, in one direction rather than cross-ripping.

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 450635



Photo 5: Photo taken from the east end of the location, facing south. Photo of interim reclamation in process.



Photo 6: Photo taken from the north side of the location, facing north. Photo shows drill pit remains open. This requires closure.

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 450635



Photo 7: Photo taken from the north side of the location, facing northwest. Photo shows drill pit remains open. This requires closure.



Photo 8: Photo taken from the east end of the location, facing north. Photo shows remaining topsoil stockpile.