

# Inspection Photos

02/12/2018

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 446515

Inspection Doc. Number: 682503154

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: GRAND MESA OPERATING CO - 35080  
Location ID: 446515



**Photo 1:** Photo of sign at well.



**Photo 2:** Photo taken from the north end of the location, facing west. Photo shows areas no longer reasonably needed for production appear to have been reduced. Topsoil appears to have been replaced. Areas appear to have been ripped for compaction alleviation. However, 1003.c requires operator to cross-rip; location appears to have only been ripped once, in one direction rather than cross-ripping. Areas within rangeland do not appear to have had revegetation activities conducted in 2017. Rig release date 8/20/2016. Interim reclamation and revegetation activities in accordance to 1003 should have been conducted by 3/20/2017.

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 446515



**Photo 3:** Photo taken from the north end of the location, facing southwest. See comments under photo 2.



**Photo 4:** Photo taken from the north end of the location, facing south. See comments under photo 2.

Inspection Photos  
Operator: GRAND MESA OPERATING CO - 35080  
Location ID: 446515



**Photo 5:** Photo taken from the north end of the location, facing southeast. See comments under photo 2.



**Photo 6:** Photo taken from the north end of the location, facing southeast. See comments under photo 2.

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 446515



**Photo 7:** Photo taken from the east end of the location, facing east. Photo shows areas where water tank sat. If areas is not reasonably needed for production, areas will also require reclamation in accordance to 1003.



**Photo 8:** Photo taken from the east end of the location, facing southwest. See comments under photo 2.

Inspection Photos  
Operator: GRAND MESA OPERATING CO - 35080  
Location ID: 446515



**Photo 9:** Photo taken from the east end of the location, facing west. See comments under photo 2.



**Photo 10:** Photo taken from the east end of the location, facing northwest. See comments under photo 2.