

Inspection Photos

02/12/2018

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 448313

Inspection Doc. Number: 682503157

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 448313



Photo 1: Photo of sign at location. .



Photo 2: Photo taken from the south end of the location, facing east. Photos 2-5 show an overview of the location from east, north to west. Photos show some reclamation activities appear to have been conducted, however, unable to find evidence that revegetation activities have been conducted in accordance to 1004.

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 448313



Photo 3:



Photo 4:

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 448313



Photo 5:



Photo 6: Photo of soils on location. Unable to find evidence that revegetation activities have been conducted in accordance to 1004.

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 448313



Photo 7: Photo taken from the access road, south of the location facing north.



Photo 8: Photo taken from the access road, south of the location facing north.

Inspection Photos

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 448313



Photo 9: Photo taken from the access road entrance, facing west. Photo show gravel (vehicle tracking BMP) has not been removed.



Photo 10: Photo taken from the access road entrance. Photo show gravel (vehicle tracking BMP) has not been removed.