

Inspection Photos
Location Name: Loustalet #B15-10
API: 05-123-15011



Photo 1: Location, looking NE



Inspection Photos
Location Name: Loustalet #B15-10
API: 05-123-15011



Photo from prior inspection for comparison



Photo 2: Wellheads, looking NW, debris cleared

Inspection Photos
Location Name: Loustalet #B15-10
API: 05-123-15011



Photo from prior inspection for comparison



Photo 3: Vaults anchored

Inspection Photos
Location Name: Loustalet #B15-10
API: 05-123-15011



Photo from prior inspection for comparison



Photo 4: Debris cleared from road