


Inspection Photos

Location Name: Rosewood Resources, Yenter C 02-21

API: 05-125-07157



1. Lease sign



2. Wellhead equipment



Inspection Photos

Location Name: Rosewood Resources, Yenter C 02-21

API: 05-125-07157



3. Meter shed



4. Meter run



Inspection Photos

Location Name: Rosewood Resources, Yenter C 02-21

API: 05-125-07157



5. Water tank 50% buried



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources