

Inspection Photos

Location Name: Rosewood Resources, Murrain 06-19

API: 05-125-07359



1. Lease sign



2. Wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rosewood Resources, Murrain 06-19

API: 05-125-07359



3. Meter shed



4. Vertical gas separators 50% buried

Inspection Photos

Location Name: Rosewood Resources, Murrain 06-19

API: 05-125-07359



5. Vertical gas separator in shed



6. Water tank 50% buried

