

# Interim Reclamation and Stormwater Inspection

February 6, 2018

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 441121

Inspection Document #: 682403314

Weld County, CO

SESE Section 32 T5N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: State Pronghorn /44-32 Pad  
Location ID: 441121



**Photo 1.** Photo taken from the southeastern location on February 6, 2018, facing West. Appears the Operator mowed Russian thistle but weed debris remains in the perimeter fences.



**Photo 2.** Photo taken from the southwestern location on February 6, 2018, facing East. See comments under Photo 1.

Inspection Photos

Location Name: State Pronghorn /44-32 Pad

Location ID: 441121



**Photo 3.** Photo taken from the western location on February 6, 2018, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: State Pronghorn /44-32 Pad  
Location ID: 441121



**Photo 4.** Photo taken from the northern location on January 12, 2018, facing East. Photo indicates unmanaged Russian thistle (*Salsola tragus*-tumbleweed) throughout the perimeter and interim areas which is considered weed debris.



**Photo 5.** Photo taken from the northern location on February 6, 2018, facing East. See comments under Photo 1.