

# Final Reclamation Inspection

February 7, 2018

Operator: NGL WATER SOLUTIONS DJ LLC - 10373

API: 05-123-16804

Inspection Document #: 682403317

Weld County, CO

SESE Section 8 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CONQUEST SWD #1-8  
API: 05-123-16804



**Photo 1.** Photo taken from an access road off CR 53 on September 13, 2017, facing East. Access road is no longer in use per Weld County requirements as described by an Operator representative. Access road will have to be reclaimed per Rule 1004.



**Photo 2.** Photo taken from an access road off CR 53 on February 7, 2018, facing East. Operator has failed to perform final reclamation activities by the corrective action date of November 15, 2017.

Inspection Photos  
Location Name: CONQUEST SWD #1-8  
API: 05-123-16804



**Photo 3.** Photo taken from the approximate central reclamation area on September 13, 2017, facing West. Photo illustrates little to no germination throughout the reclamation area. Most of the green foliage in the photo is that of Russian thistle/Kochia.



**Photo 4.** Photo taken from the approximate central reclamation area on February 7, 2018, facing West. Weedy, annual vegetation remains (Russian thistle/Kochia). Operator has failed to perform final reclamation activities by the corrective action date of November 15, 2017.

Inspection Photos  
Location Name: CONQUEST SWD #1-8  
API: 05-123-16804



**Photo 5.** Photo taken from the western reclamation area on September 13, 2017, facing West. Photo illustrates a patch of desirable vegetative growth mixed with Russian thistle.



**Photo 6.** Photo taken from the western reclamation area on February 7, 2018, facing West. See comments under Photo 4.

Inspection Photos  
Location Name: CONQUEST SWD #1-8  
API: 05-123-16804



**Photo 7.** Photo taken from the western reclamation area on February 7, 2018, facing West. See comments under Photo 4.



**Photo 8.** Reference photo taken just west of the western reclamation area. Photo illustrates the vegetative growth that is not reflective throughout the reclamation area.