

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2018

Submitted Date:

02/14/2018

Document Number:

677400563**FIELD INSPECTION FORM**Loc ID 305668 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280879	WELL	SI	09/01/2017	GW	123-23328	LEFFLER 1 21-2	PA

General Comment:Well was PA on Oct 2017 that is all the information I have.

Inspected Facilities									
Facility ID:	280879	Type:	WELL	API Number:	123-23328	Status:	SI	Insp. Status:	PA

COGCC Comments		
Comment	User	Date
High Risk Inspection, well was out in plowed muddy field and PA on Oct 2107 That is all the information I have on this well	montoyaj	02/14/2018