

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2018

Submitted Date:

02/15/2018

Document Number:

679904026**FIELD INSPECTION FORM**
 Loc ID 321240 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 81480Name of Operator: THOMAS L SPRING LLCAddress: 7400 E ORCHARD RD STE 106-SCity: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Springs, Tom	303-771-1889 off/68710	T1spring@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257026	WELL	PR	11/01/2017	GW	011-06172	WOLLERT B 3	PR

General Comment:[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road to farm house		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank and metal sign by tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to stairs at tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	HGS on north side of meter run		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		38.225590,-102.765140
Comment:	Steel tank on south side of open top tank				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Berms need maintenance for capacity						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	Open Top		38.225590,-102.765140	
Comment: 60bbl fiberglass open top water tank w/Adequate wildlife screening						
Corrective Action:					Date:	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shared berms						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID: 257026	Type: WELL	API Number: 011-06172	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Well is SI at time of inspection			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Location is farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT