

Inspection Photos – February 9, 2018
Shook Location #448269
PetroShare Corporation #10454



Bentonitic fluids land application area adjacent SE side of Shook Pad.



Dried bentonitic fluids on surface.

Inspection Photos – February 9, 2018
Shook Location #448269
PetroShare Corporation #10454



Land application area looking east towards the Weigandt 43-3 (001-09095)



Land application area looking west toward the Shook Pad.

Inspection Photos – February 9, 2018
Shook Location #448269
PetroShare Corporation #10454



Shook well pad looking west.