

# Inspection Photos

02/15/2018

Operator: ENERVEST OPERATING LLC - 10098

Location ID: 320158

Inspection Doc. Number: 682503168

Adams County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: ENERVEST OPERATING LLC - 10098  
Location ID: 320158



**Photo 1:** Photo taken from the well location, facing north.



**Photo 2:** Photo taken from the well location, facing east.



Inspection Photos  
Operator: ENERVEST OPERATING LLC - 10098  
Location ID: 320158



**Photo 3:** Photo taken from the well location, facing south.



**Photo 4:** Photo taken from the well location, facing west.



Inspection Photos  
Operator: ENERVEST OPERATING LLC - 10098  
Location ID: 320158




**Photo 5:** Photo taken from the east end of the former tank battery facility, facing west. Photo shows riser remaining at the battery location. Previous inspections required operator to remove riser in accordance to 1004.a; corrective action has not been addressed. Photo also shows riser equipment appears to be interfering with surface owners agricultural activities.



**Photo 6:** Photo taken from the south end of the former tank battery facility, facing north. Photo shows riser remaining at the battery location. Previous inspections required operator to remove riser in accordance to 1004.a; corrective action has not been addressed. Photo also shows riser equipment appears to be interfering with surface owners agricultural activities.




Inspection Photos  
Operator: ENERVEST OPERATING LLC - 10098  
Location ID: 320158



**Photo 5:** 2010 aerial imagery. Photo shows the well location and tank battery facility location.



Inspection Photos  
Operator: ENERVEST OPERATING LLC - 10098  
Location ID: 320158



**Photo 6:** 2013 Aerial imagery. Records indicate well was plugged and abandoned in 2012. Photo shows well area of the tank battery facility were riser remains.