

Inspection Photos

API: 05-067-07611

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602494

Inspection Date: 2/5/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*) and dropseed (*Sporobolus* sp.).



Photo 3. View of the southern portion of the working area from the southwestern corner facing eastward.



Photo 4. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 5. View large Scotch thistle (*Onopordum acanthium*) in the southwestern portion of the project area.