

Inspection Photos

API: 05-067-09715

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602500

Inspection Date: 2/5/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing with grasses such as blue grama (*Bouteloua gracilis*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the western portion of the working area from the southwestern corner facing northward.



Photo 4. View of the eastern portion of the project area from the northeastern corner facing southward.