

Inspection Photos

API: 05-067-05414

Operator: LOGOS OPERATING LLC

Inspection Number: 680602496

Inspection Date: 2/5/2018



Photo 1. View of the project area from the southern edge facing center teardrop.



Photo 2. View of meterhouse along the southeastern edge of the project area.



Photo 3. View of project facilities in the southwestern portion of the project area from the southern edge facing westward.



Photo 3. Kochia debris in the southern portion of the project area.