

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2018

Submitted Date:

02/21/2018

Document Number:

679904048**FIELD INSPECTION FORM**

Loc ID 304534 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 264445 | WELL | PR | 10/04/2002 | GW | 125-08669 | HELLING BROS 23-8443 | PR |

General Comment:[Routine Inspection](#)

Location

| | | | |
|--------------------|---------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road through farm ground | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|-------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence at unit | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|---------------------------------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit and wellhead | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Tank is 3/4 fenced with wire | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | |
|----------------------|------------------------------|-----------------------|------------|------------------|
| Facility ID: 264445 | Type: WELL | API Number: 125-08669 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing. Casing production | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT