

Grynberg Petroleum Company

Status Update

Croissant Lease

Point ID 454026 and 454026

NW section 26 9N 62W

Pending Operations

- Mechanical Integrity Test
 - Croissant 1 UIC
 - Croissant 4
 - Graefe 1
- Line testing for dead vegetation investigation
- Tank battery stain remediation
- Separator and treater stain remediation
- Remediate soil at release point 454026
- Remediate soil at release point 454027
- Perform work to return lease to production and injection