



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 25, 2018 12:29:36 PM MST
Server Receive Date:	Jan 25, 2018 12:29:42 PM MST
Reference Number:	20180125-1872281534
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA Jan 25, 2018 12:29:00 PM MST [View Map]

Information

Name	reclamationtablet
Date	Jan 23, 2018
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	NW team
Well Name	MAYFIELD GAS UNIT A 1
API Number	50670655900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Completed work description

mowed/removed Russian thistle and kochia debris