

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Feb 8, 2018 12:47:17 PM MST
Server Receive Date:	Feb 8, 2018 12:47:24 PM MST
Reference Number:	20180208-1872902164
Location:	682 Dreamy Draw, Durango, CO 81303, USA Feb 8, 2018 12:46:37 PM MST [View Map]

Information

Name	reclamationtablet
Date	Feb 8, 2018
Location Name (Other)	helen craig 1
Location API (Other)	0506706960
Select State	Colorado
Action Complete	Fencing Clean up Operator Debris Clean Up Land Owner Debris Spot seeding

Picture South to North



Picture West to East



Additional photos



Additional photos



Completed work description

cleaned up concrete and pipe on site seeded the northeast corner and built fencing