

Inspection Photos
Location Name: Birds of Prey #36-10-61
Location ID: 420207



Photo 1: Wellhead, looking E



Photo 2: Location, looking N

Inspection Photos
Location Name: Birds of Prey #36-10-61
Location ID: 420207



Photo 3: Low berms



Photo 4: Weeds in berms, inside tank battery

Inspection Photos
Location Name: Birds of Prey #36-10-61
Location ID: 420207



Photo 5: Stained soil at wellhead