

Inspection Photos

Loc# 334947

Operator: Terra

Inspection Number: 680102704

Inspection Date: 2/22/2018



Photo#1:
View over Location to Northwest.

February 22, 2018



Photo#2:

There is unused equipment stored on Fill Slope Berm adjacent to Entry. Arrow indicates Sediment trap detailed in Photo #3..

February 22, 2018



Photo#3:
Close up of Sediment trap & Drain ; position shown in Photo #1 .

February 22, 2018



Photo#4:
Subsidence in Ditch leading to Sediment Trap.
Arrow indicates Sediment Trap.



Photo#5:
Position of Subsidence in relation to Tank Facility

February 22, 2018



Photo#6:

Point at base of Fill Slope where SW is exiting from Subsidence above.

February 22, 2018