

# *Inspection Photos*

*Loc# 335253*

*Operator: Terra*

*Inspection Number: 680102708*

*Inspection Date: 2/22/2018*





Photo#1:  
View over Location to Southeast..

February 22, 2018



Photo#2:

Storm water is Under cutting armoring/rip rap of drains into & out of Sediment traps.

Photo#3:

February 22, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photo:TEP Loc# 335253 Barret ET AL