

# Construction and Stormwater Inspection

February 22, 2018

Operator: SRC ENERGY INC- #10311

Location ID: 453978

Inspection Document #: 682403330

Weld County, CO

SWNE Section 15 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Harvesters State /7-15 Pad  
Location ID: 453978



**Photo 1.** Photo taken from the northern location, facing East. Operator has installed a ditch and berm BMP around the perimeter of the location, in addition to retention areas and sediment traps.



**Photo 2.** Photo taken from the northern location, facing West. See comments under Photo 1.

# Inspection Photos

Location Name: Harvesters State /7-15 Pad

Location ID: 453978



**Photo 3.** Photo taken from the northern location, facing Southeast. Appears topsoil has been salvaged and stored along the eastern perimeter of the location.

Inspection Photos  
Location Name: Harvesters State /7-15 Pad  
Location ID: 453978



**Photo 4.** Photo taken from the western location, facing South. Operator has installed a retention area in conjunction with the ditch and berm BMP.



**Photo 5.** Photo taken from the southwest location, facing East. See comments under Photo 4.

Inspection Photos  
Location Name: Harvesters State /7-15 Pad  
Location ID: 453978



**Photo 6.** Photo taken from the southern location, facing East. Operator has installed a sediment trap in conjunction with the ditch and berm BMP.



**Photo 7.** Photo taken from the southeast location, facing East. See comments under Photo 6.

Inspection Photos  
Location Name: Harvesters State /7-15 Pad  
Location ID: 453978



**Photo 8.** Photo taken from the southeastern location, facing North. See comments under Photo 1 & 3.



**Photo 9.** Photo taken from the eastern location, facing North. See comments under Photo 4.