

Construction and Stormwater Inspection

February 22, 2018

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 453331

Inspection Document #: 682403332

Weld County, CO

SWSE Section 27 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: G & D Hanks /27-N Pad
Location ID: 453331



Photo 1. Photo taken from the western location, facing North. Operator has installed a ditch and berm BMP around the perimeter of the location. Portions of the berm BMP along the southern location have not been properly stabilized.



Photo 2. Photo taken from the southern location, facing East. See comments under Photo 1.

Inspection Photos

Location Name: G & D Hanks /27-N Pad

Location ID: 453978



Photo 3. Photo taken from the southern location, facing North. Operator is IN-PROCESS of topsoil salvage operations. Appears frozen soil conditions are evident with large sections of soil material being uplifted during salvage operations.

Inspection Photos
Location Name: G & D Hanks /27-N Pad
Location ID: 453331



Photo 4. Photo taken from the eastern location, facing North. See comments under Photo 1.



Photo 5. Photo taken from the northeast location, facing West. See comments under Photo 1.