

Well Name : Allison Unit 116T
API # : 067-09551




Photo 1: Wellhead sign.



Photo 2: Equipment at S end of tank battery previous inspection.

Well Name : Allison Unit 116T
API # : 067-09551



Photo 3: Equipment removed.



Photo 4: Batteries inside compressor building previous inspection.

Well Name : Allison Unit 116T
API # : 067-09551



Photo 5: Battery outside compressor building.



Photo 6: Battery inside compressor building.

Well Name : Allison Unit 116T
API # : 067-09551



Photo 7: Battery inside compressor building.



Photo 8: Impacted soil at compressor skid.