

FORM 5A

Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 401534984

Date Received: 02/28/2018

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 10433
2. Name of Operator: LARAMIE ENERGY LLC
3. Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202
4. Contact Name: Joan Proulx
Phone: (970) 263-3641
Fax:
Email: jproulx@laramie-energy.com

5. API Number 05-077-09007-00
6. County: MESA
7. Well Name: GUNDERSON
Well Number: 13-5
8. Location: QtrQtr: NESW Section: 13 Township: 9S Range: 94W Meridian: 6
9. Field Name: BRUSH CREEK Field Code: 7562

Completed Interval

FORMATION: CORCORAN Status: TEMPORARILY ABANDONED Treatment Type:
Treatment Date: End Date: Date of First Production this formation:
Perforations Top: 8292 Bottom: 8327 No. Holes: 12 Hole size: 34/100
Provide a brief summary of the formation treatment: Open Hole: [X]
This formation is commingled with another formation: [X] Yes [] No
Total fluid used in treatment (bbl): Max pressure during treatment (psi):
Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):
Type of gas used in treatment: Min frac gradient (psi/ft):
Total acid used in treatment (bbl): Number of staged intervals:
Recycled water used in treatment (bbl): Flowback volume recovered (bbl):
Fresh water used in treatment (bbl): Disposition method for flowback:
Total proppant used (lbs): Rule 805 green completion techniques were utilized: []
Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: Hours: Bbl oil: Mcf Gas: Bbl H2O:
Calculated 24 hour rate: Bbl oil: Mcf Gas: Bbl H2O: GOR:
Test Method: Casing PSI: Tubing PSI: Choke Size:
Gas Disposition: Gas Type: Btu Gas: API Gravity Oil:
Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:

Reason for Non-Production: TAd for drilling operations

Date formation Abandoned: 02/04/2018 Squeeze: [] Yes [] No If yes, number of sacks cmt

** Bridge Plug Depth: 6154 ** Sacks cement on top: ** Wireline and Cement Job Summary must be attached.

FORMATION: WILLIAMS FORK - CAMEO Status: TEMPORARILY ABANDONED Treatment Type: _____

Treatment Date: _____ End Date: _____ Date of First Production this formation: _____

Perforations Top: 6230 Bottom: 7644 No. Holes: 114 Hole size: 34/100

Provide a brief summary of the formation treatment: _____ Open Hole:

This formation is commingled with another formation: Yes No

Total fluid used in treatment (bbl): _____ Max pressure during treatment (psi): _____

Total gas used in treatment (mcf): _____ Fluid density at initial fracture (lbs/gal): _____

Type of gas used in treatment: _____ Min frac gradient (psi/ft): _____

Total acid used in treatment (bbl): _____ Number of staged intervals: _____

Recycled water used in treatment (bbl): _____ Flowback volume recovered (bbl): _____

Fresh water used in treatment (bbl): _____ Disposition method for flowback: _____

Total proppant used (lbs): _____ Rule 805 green completion techniques were utilized:

Reason why green completion not utilized: _____

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: _____ Hours: _____ Bbl oil: _____ Mcf Gas: _____ Bbl H2O: _____

Calculated 24 hour rate: _____ Bbl oil: _____ Mcf Gas: _____ Bbl H2O: _____ GOR: _____

Test Method: _____ Casing PSI: _____ Tubing PSI: _____ Choke Size: _____

Gas Disposition: _____ Gas Type: _____ Btu Gas: _____ API Gravity Oil: _____

Tubing Size: _____ Tubing Setting Depth: _____ Tbg setting date: _____ Packer Depth: _____

Reason for Non-Production: TAd for drilling operations

Date formation Abandoned: 02/04/2018 Squeeze: Yes No If yes, number of sacks cmt _____

** Bridge Plug Depth: 6154 ** Sacks cement on top: _____ ** Wireline and Cement Job Summary must be attached.

Comment:

The Gunderson 13-13 well was temporarily abandoned on 02/01/2018. Four of the six producing wells on the pad will be TAd as drilling operations for 21 new wells are expected to begin shortly.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Joan Proulx

Title: Regulatory Analyst Date: 2/28/2018 Email: jproulx@laramie-energy.com

Attachment Check List

Att Doc Num	Name
401534984	FORM 5A SUBMITTED
401557836	WIRELINE JOB SUMMARY

Total Attach: 2 Files

General Comments

User Group	Comment	Comment Date
Permit	-Changed bridge plug depth to match wireline survey.	03/01/2018

Total: 1 comment(s)