

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2018

Submitted Date:

03/01/2018

Document Number:

688301302**FIELD INSPECTION FORM**
 Loc ID 451166 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|----------------|---------------------------------------|--|
| Strickler, Robert | | Robert.D.Strickler@conocophillips.com | All DJ Basin Inspections |
| Gahr, Dean | (303) 268-3723 | Dean.P.Gahr@conocophillips.com | All DJ Basin Inspections |
| Dixon, Jennifer | (701) 264-2041 | jennifer.a.dixon@conocophillips.com | Regulatory Coordinator |
| ConocoPhillips | | COPColoradoReg@conocophillips.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 453492 | WELL | DG | 02/27/2018 | | 001-10100 | Big Sandy 3-65 36-31 2BH | DG |

General Comment:[Surface Cementing Inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|------------------------|-------|--|
| Type | DRILLING/RECOMP | | |
| Comment: | At Hudson Rd and Cofax | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------|-------|--|
| Comment: | 855-595-8258 | Date: | |
| Corrective Action: | | | |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------|-------|--|
| Type | LOCATION | | |
| Comment: | barbed wire | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 453492 Type: WELL API Number: 001-10100 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: Nabors Rig 16 Pusher/Rig Manager: Richard Perez
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: NO Unlined Pit: NO Closed Loop: YES Semi-Closed Loop: NO
 Multi-Well: YES Disposal Location: offsite disposal

Comment: Surface TD 2108'

Corrective Action: _____

Date: _____

Cement**Cement Contractor**

Contractor Name: Halliburton Contractor Phone: _____

Surface Casing

Cement Volume (sx): 705 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: 2/28/2018, ~9:15 pm start
455 sxs, 12 ppg lead cement, pumped @ ~330 psi and ~8 bpm
250 sxs, 14.2 ppg tail cement, pumped @ @390 psi and ~4 bpm
159 BBLs water to displace

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Self Inspection | Pass | |
| Compaction | Pass | Compaction | Pass | Covering Materials | Pass | |
| Gravel | Pass | Gravel | Pass | Material Handling And Spill Prevention | Pass | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 688301303 | ConocoPhillips Big Sandy 3-65 36-31 2BH | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4391330 |