

# *Inspection Photos*

*Loc#446582*

*Operator: Ursa*

*Inspection Number: 680102738*

*Inspection Date: 2/27/2018*





Photo#1:  
View of Location inside Sound Walls



Photo#2:  
View of Landscaping installed along East Berm

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa BMC D Pad Loc#446582



Photo#3:  
View along East perimeter of Pad & Sound Wall



Photo#4:  
View along South Pad Perimeter & Sound Wall

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa BMC D Pad Loc#446582



Photo#5:  
Area where Stormwater is starting to undercut Wattles.  
\*



Photo#6:  
Arrow indicates where BMP Failure (Photo #5) is located;  
on outside of Fence & backside of straw bales.

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa BMC D Pad Loc#446582



**Photo#7:**

Area on North west Perimeter where Stormwater is starting to Channel under Fence..

February 27, 2018