

# *Inspection Photos*

*Loc#447695*

*Operator: Ursa*

*Inspection Number: 680102739*

*Inspection Date: 2/27/2018*



Photo#1:  
View North from Access Rd into Location.



Photo#2:  
View of Location inside Sound Walls

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa BMC B Pad Loc#447695



Photo#3:  
View South along ditch on East side of Access Rd;  
BMPs have been Compromised.

\*

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#4:  
View South of Ditch on East side of Access Rd; arrow  
indicates spot where Material pile is blocking SW  
flow and Drain.

Inspection Photos: Ursa BMC B Pad Loc#447695



Photo#5:  
Close up view of blocked ditch & drain in Photo#4 .



Photo#6:  
Looking back (Southwest) at blocked BMP

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa BMC B Pad Loc#447695



Photo#7:



Photo#8:

Sediment is migrating off slope on North side of Location; area will need attention.

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa BMC B Pad Loc#447695



Photo#9:

Open Riser outside Sound Walls on North side of Location, houses Valves and top is open.

Photo#10:

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa BMC B Pad Loc#447695