

# Inspection Photos

API: 05-067-07202

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602506

Inspection Date: 2/26/2018



**Photo 1. View of the project area from the northwestern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward. Working area is fenced. Surface owner is storing equipment adjacent to the eastern edge of the project area. Berms are revegetating with grasses such as sand dropseed (*Sporobolus cryptandrus*).**



**Photo 3. View of the western portion of the project area from the northwestern corner facing southward.**



**Photo 4. View of the southeastern portion of the project area from the southeastern corner facing westward. Irrigation canal runs adjacent to southern edge.**



Photo 5. View of kochia debris in the southeastern portion of the project area.