

Inspection Photos

API: 05-067-08351

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602508

Inspection Date: 2/26/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is sparse with grasses such as western wheatgrass (*Pascopyrum smithii*) and intermediate wheatgrass (*Thinopyron intermedium*). This needs monitoring.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 4. View of the northern portion of the project area from the northeastern corner facing westward. Slope is reduced and revegetation is progressing here.