

**Inspection Photos**  
**Location Name: Hill #8-3**  
**API: 05-067-08502**



**Aztec Rig #840.**



**PA marker for Hill #1-8 with PVC soil vapor tube.**

**Inspection Photos**  
**Location Name: Hill #8-3**  
**API: 05-067-08502**



**Label on container is faded and worn. No NFPA placard.**



**Weeds present within secondary containment berm.**

**Inspection Photos**  
**Location Name: Hill #8-3**  
**API: 05-067-08502**



**Drip pot on load out line.**



**Spill prevention underneath rig engine.**