

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
02/27/2018

Submitted Date:  
02/27/2018

Document Number:  
689701107

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
335901 \_\_\_\_\_ LONGWORTH, MIKE \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

27 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297475	WELL	PR	10/05/2009	GW	045-16853	N. PARACHUTE EF15B D19B 595	PR
297825	WELL	PR	10/13/2009	GW	045-16969	N. PARACHUTE EF06C D19B 595	PR
297826	WELL	PR	11/01/2009	GW	045-16970	N. PARACHUTE EF10D D19B 595	PR
297827	WELL	PR	10/04/2009	GW	045-16971	N. PARACHUTE EF14C D19B 595	PR
297828	WELL	PR	11/01/2009	GW	045-16972	N. PARACHUTE EF07D D19B 595	PR
297829	WELL	PR	11/01/2009	GW	045-16973	N. PARACHUTE EF06D D19B 595	PR
297830	WELL	PR	11/01/2009	GW	045-16974	N. PARACHUTE EF10C D19B 595	PR
297831	WELL	PR	11/01/2009	GW	045-16975	N. PARACHUTE EF10B D19B 595	PR
297833	WELL	PR	11/01/2009	GW	045-16976	N. PARACHUTE EF10A D19B 595	PR
297834	WELL	PR	10/04/2009	GW	045-16977	N. PARACHUTE EF14A D19B 595	PR
297836	WELL	PR	10/04/2009	GW	045-16978	N. PARACHUTE EF15A D19B 595	PR
297837	WELL	PR	12/01/2009	GW	045-16979	N. PARACHUTE EF08C D19B 595	PR
297838	WELL	PR	12/01/2009	GW	045-16980	N. PARACHUTE EF08B D19B 595	PR
297839	WELL	PR	12/01/2009	GW	045-16981	N. PARACHUTE EF03D D19B 595	PR
297840	WELL	PR	12/01/2009	GW	045-16982	N. PARACHUTE EF02D D19B 595	PR
297841	WELL	PR	06/06/2008	GW	045-16983	N. PARACHUTE EF04B D19B 595	PR

297842	WELL	PR	11/01/2009	GW	045-16984	N. PARACHUTE EF06A D19B 595	PR
298923	WELL	PR	10/25/2009	GW	045-17475	N. PARACHUTE EF11B D19B 595	PR
298924	WELL	PR	10/04/2009	GW	045-17476	N. PARACHUTE EF11C D19B 595	PR
298925	WELL	PR	09/29/2009	GW	045-17477	N. PARACHUTE EF14B D19B 595	PR
298926	WELL	PR	12/01/2009	GW	045-17478	N. PARACHUTE EF07B D19B 595	PR
298927	WELL	PR	10/03/2009	GW	045-17479	N. PARACHUTE EF11D D19B 595	PR
298928	WELL	PR	12/01/2009	GW	045-17480	N. PARACHUTE EP07C D19B 595	PR
298936	WELL	PR	10/04/2009	GW	045-17481	N. PARACHUTE EF11A D19B 595	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	970-285-2615		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 3		
Comment:	Chemical containers		
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	297475	Type:	WELL	API Number:	045-16853	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297825	Type:	WELL	API Number:	045-16969	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297826	Type:	WELL	API Number:	045-16970	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297827	Type:	WELL	API Number:	045-16971	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297828	Type:	WELL	API Number:	045-16972	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297829	Type:	WELL	API Number:	045-16973	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297830	Type:	WELL	API Number:	045-16974	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297831	Type:	WELL	API Number:	045-16975	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 297833	Type: WELL	API Number: 045-16976	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 297834	Type: WELL	API Number: 045-16977	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 297836	Type: WELL	API Number: 045-16978	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 297837	Type: WELL	API Number: 045-16979	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 297838	Type: WELL	API Number: 045-16980	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 297839	Type: WELL	API Number: 045-16981	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 297840	Type: WELL	API Number: 045-16982	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 297841	Type: WELL	API Number: 045-16983	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	

Facility ID: 297842	Type: WELL	API Number: 045-16984	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 298923	Type: WELL	API Number: 045-17475	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 298924	Type: WELL	API Number: 045-17476	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 298925	Type: WELL	API Number: 045-17477	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 298926	Type: WELL	API Number: 045-17478	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 298927	Type: WELL	API Number: 045-17479	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 298928	Type: WELL	API Number: 045-17480	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 298936	Type: WELL	API Number: 045-17481	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401557709	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388277">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388277</a>
689701108	Inspection 689701107 photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388238">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388238</a>