

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2018

Submitted Date:

02/27/2018

Document Number:

689701109

**FIELD INSPECTION FORM**

Loc ID 335579 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

31 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
29	WELL	PR	01/02/2007	GW	045-11674	N. PARACHUTE EF05D E19 595	PR
282300	WELL	PR	03/31/2008	GW	045-11711	N. PARACHUTE E02C-24 E19 595	PR
282301	WELL	PR	12/29/2005	GW	045-11712	N. PARACHUTE EF05C E19 595	PR
282302	WELL	PR	03/27/2008	GW	045-11713	N. PARACHUTE EF02D-24 E19 59	PR
282303	WELL	PR	02/25/2008	GW	045-11714	N.PARACHUTE EF05B-19 E19 59	PR
282304	WELL	PR	01/12/2007	GW	045-11715	N.PARACHUTE EF09B E19 595	PR
282305	WELL	PR	02/01/2014	GW	045-11716	N.PARACHUTE EF09D E19 595	PR
282306	WELL	PR	01/04/2007	GW	045-11717	N. PARACHUTE EFO5B E19 595	PR
291668	WELL	PR	05/27/2008	GW	045-14492	N. PARACHUTE EF09A-24 E19 59	PR
291669	WELL	PR	07/06/2008	GW	045-14491	N. PARACHUTE EF10A-24E19 595	PR
291670	WELL	PR	06/07/2008	GW	045-14490	N. PARACHUTE EF10B-24E19 595	PR
291671	WELL	PR	07/31/2007	GW	045-14489	N. PARACHUTE EF10C-24E19 595	PR
291672	WELL	PR	07/31/2007	GW	045-14488	N.PARACHUTE EF08C-24 E19 59	PR
291674	WELL	PR	07/31/2007	GW	045-14478	N. PARACHUTE EF10D-24E19 595	PR
291675	WELL	PR	11/16/2008	GW	045-14479	N.PARACHUTE EF02B-24 E19 59	PR
291676	WELL	PR	11/06/2008	GW	045-14480	N.PARACHUTE EF08B-24 E19 59	PR

291677	WELL	PR	06/21/2008	GW	045-14481	N.PARACHUTE EF08D-24 E19 59	PR
291681	WELL	PR	02/01/2011	GW	045-14486	N.PARACHUTE EF07B-24 E19 59	PR
291682	WELL	PR	11/13/2008	GW	045-14487	N.PARACHUTE EF07A-24 E19 59	PR
291683	WELL	PR	11/09/2008	GW	045-14485	N. PARACHUTE EF01D-24 E19 59	PR
291684	WELL	PR	11/17/2008	GW	045-14484	N. PARACHUTE EF01B-24 E19 59	PR
291685	WELL	PR	07/03/2008	GW	045-14483	N. PARACHUTE EF07D- 24E19 595	PR
291686	WELL	PR	11/07/2008	GW	045-14482	N. PARACHUTE EF07C-24 E19 59	PR
292401	WELL	PR	11/01/2008	GW	045-14719	N. PARACHUTE EF08A-24 E19 59	PR
292449	WELL	PR	11/07/2008	GW	045-14725	N. PARACHUTE EF 16A-24 E19 5	PR
292450	WELL	PR	11/07/2008	GW	045-14724	N. PARACHUTE EF09C-24 E19 59	PR
293205	WELL	PR	11/20/2008	GW	045-14924	N.PARACHUTE EF02A-24 E19 59	PR
293206	WELL	PR	11/20/2008	GW	045-14925	N.PARACHUTE EF01A-24 E19 59	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	970-285-2615		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	Chemical containers		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	29	Type:	WELL	API Number:	045-11674	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282300	Type:	WELL	API Number:	045-11711	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282301	Type:	WELL	API Number:	045-11712	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282302	Type:	WELL	API Number:	045-11713	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282303	Type:	WELL	API Number:	045-11714	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282304	Type:	WELL	API Number:	045-11715	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282305	Type:	WELL	API Number:	045-11716	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282306	Type:	WELL	API Number:	045-11717	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 291668	Type: WELL	API Number: 045-14492	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291669	Type: WELL	API Number: 045-14491	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291670	Type: WELL	API Number: 045-14490	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291671	Type: WELL	API Number: 045-14489	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291672	Type: WELL	API Number: 045-14488	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291674	Type: WELL	API Number: 045-14478	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291675	Type: WELL	API Number: 045-14479	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291676	Type: WELL	API Number: 045-14480	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:

Facility ID: 291677	Type: WELL	API Number: 045-14481	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291681	Type: WELL	API Number: 045-14486	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291682	Type: WELL	API Number: 045-14487	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291683	Type: WELL	API Number: 045-14485	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291684	Type: WELL	API Number: 045-14484	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291685	Type: WELL	API Number: 045-14483	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291686	Type: WELL	API Number: 045-14482	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 292401	Type: WELL	API Number: 045-14719	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	

Facility ID: <u>292449</u>	Type: <u>WELL</u>	API Number: <u>045-14725</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>Producing well</u>	
Corrective Action:	Date:

Facility ID: <u>292450</u>	Type: <u>WELL</u>	API Number: <u>045-14724</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>Producing well</u>	
Corrective Action:	Date:

Facility ID: <u>293205</u>	Type: <u>WELL</u>	API Number: <u>045-14924</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>Producing well</u>	
Corrective Action:	Date:

Facility ID: <u>293206</u>	Type: <u>WELL</u>	API Number: <u>045-14925</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>Producing well</u>	
Corrective Action:	Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401557710	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388278">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388278</a>
689701110	iNSPECTION 689701109 photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388239">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388239</a>