

Inspection Photos

API: 05-067-07431

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602511

Inspection Date: 2/26/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is sparse with grasses such as western wheatgrass (*Pascopyrum smithii*) and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the western portion of the project area from the southwestern corner facing northward.



Photo 4. View of the northern portion of the project area from the northwestern edge facing eastward. Slope is reduced and revegetation is progressing here.