Inspection Photos
Location Name: Lucero 34-10
API: 05-123-17156
Inspection Date: 03/07/2018

Photo 1 – Wellhead sign

Photo 2 – Looking west along flowline trench from wellhead toward spill ID 454050.

Inspection Photos
Location Name: Lucero 34-10
API: 05-123-17156
Inspection Date: 03/07/2018

Photo 3 – View of flowline trench at wellhead.

Photo 4 – Removed steel flowlines, looking west.

Inspection Photos
Location Name: Lucero 34-10
API: 05-123-17156
Inspection Date: 03/07/2018

Photo 5 – Removed steel flowlines, coated and joints wrapped.

Photo 6 – Removed steel flowlines looking east.

Inspection Photos
Location Name: Lucero 34-10
API: 05-123-17156
Inspection Date: 03/07/2018

Photo 7 – View into excavation at spill ID 454050, looking west.

Photo 8 – View into excavation at spill ID 454050, looking southeast.

Inspection Photos
Location Name: Lucero 34-10
API: 05-123-17156
Inspection Date: 03/07/2018

Photo 9 – View of exposed trench at spill ID 454029.

Photo 10 – View of removed flowline joint at spill ID 454050.