

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2018

Submitted Date:

03/07/2018

Document Number:

679904103**FIELD INSPECTION FORM**

Loc ID 336763 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 279021 | WELL | PR | 06/01/2015 | GW | 125-09383 | RENZELMAN 10-22 | PR |

General Comment:[Routine Inspection](#)

Location**Lease Road:**

| | | | |
|--------------------|---------------------------------|-------|--|
| Type | Access | | |
| comment: | Access wellhead through pasture | | |
| Corrective ActionL | | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|--|-------|--|
| Type | WELLHEAD | | |
| Comment: | Lease sign by wellhead. Update to current operator | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | Date: _____ |
| Corrective Action: | | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 279021 | Type: | WELL | API Number: | 125-09383 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (Renzelman 4-22, 8-22, 9-22, 10-22, 12-23, 15-22, 16-22 & Noble DP) 2150' S @ Renzelman 4-22 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|
| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | Pass | | | | | |

Comment: Location is grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT