




View Looking East Over
Back-filled Pit Site



View Looking West Over
Back-filled Pit Site

Diamond Operating Inc.
Decker Skim Pit Closure Project
COGCC Remediation #8697

Photos After Final Pit Site Closure