

# Final Reclamation Inspection

March 9, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-001-09191

Inspection Document #: 682403389

Adams County, CO

NESE Section 2 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NEWLANDER G UNIT #1  
API: 05-001-09191



**Photo 1.** Photo taken from the facility/well location, facing West. No visual evidence of equipment on location. Well was plugged 6/25/2017. Final land use change to housing development.



**Photo 2.** Photo taken from the facility/well location, facing East. See comments under Photo 1.