

# Inspection Photos

03/12/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 305414

Inspection Doc. Number: 682503200

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 305414



**Photo 1:** Photo taken from the west end of the location, facing east. Photo shows additional reclamation activities appear to have been conducted.



**Photo 2:** Photo taken from the west end of the location, facing north. Photo shows additional reclamation activities appear to have been conducted.



**Photo 3:** Photo taken from access road, facing north. Photo shows additional reclamation activities appear to have been conducted.



**Photo 4:** Photo taken from the access road. Photo shows cattle guard has not been removed, though maintenance appears to have been conducted. Sundry #401502788, operator states “surface owner does not want BMP removed and is in the process of filing paperwork to accommodate request”. At time of inspection, no variance has been submitted, location will remain out of compliance until variance request has been approved or BMP removed per CA