

# Inspection Photos

03/12/2018

Operator: WHITING OIL & GAS CORPORATION -  
96155

Location ID: 331145

Inspection Doc. Number: 682503206  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 331145



**Photo 1:** Photo taken from the east end of the location, facing north. Photo shows the reclamation area.



**Photo 2:** Photo taken from the east end of the location, facing west. Photo shows the reclamation area.

Inspection Photos  
Operator: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 331145



**Photo 3:** Photo taken from the location, facing west. Photo shows location does not meet reclamation standards, however germination and vegetative establishment is evident. Additional time may be required.



**Photo 4:** Photo taken from the access road, facing east. Germination and vegetative establishment is evident, however reclamation on the road does not appear to be progressing and supplemental reclamation will likely be required.