

Inspection Photos
Graham #13-8 (A13w)
API: 05-045-07381
Inspection Number: 689300641



Photo # 1 Hole in Tank Containment




Photo #2 Hole in Tank Containment

Inspection Photos
Graham #13-8 (A13w)
API: 05-045-07381
Inspection Number: 689300641

East Elevation

● 39°27'6"N, 107°43'0"W ±16.4ft



27 Feb 2018, 11:47 AM

Photo #3 Hole in Tank Containment

North East Elevation

● 39°27'6"N, 107°43'0"W ±16.4ft



27 Feb 2018, 11:47 AM

Photo #4 Hole in Tank Containment

Inspection Photos
Graham #13-8 (A13w)
API: 05-045-07381
Inspection Number: 689300641

North Elevation

☉ 39°27'6"N, 107°43'0"W ±16.4ft



Photo #5 Entrance Looking South



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources